Oil Field Environmental Incident Summary

Responsible Party: Liberty Resources LLC
Well Operator: LIBERTY RESOURCES LLC
Well Name: J. D. GANNAWAY FEDERAL 1

Field Name: GLASS BLUFF Well File #: 11827

Date Incident:1/10/2014Time Incident:09:00Facility ID Number:County:WILLIAMSTwp:152Rng:103Sec:19Qtr:

Location Description:

Submitted By: Christopher Clark Received By:

Contact Person: Chris Clark

1200 17TH ST STE 2050 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup Units

	Opinou	Omico	7100070704	Omio
Oil	4	barrels	4	barrels
Brine	30	barrels	30	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Spill was mostly contained within dike. Some water escaped dike and was contained on the well pad and above the frozen ground. Spill was cleaned up by mid-day and spilled fluids were returned to production tanks. Dike integrity will be mitigated with new clay or liner to prevent future incident.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater popoff, remained on location, according to the report. NDIC retains oversight.